



U.S. Department of Transportation


National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.





Case Vehicle (A): 1998 Chevrolet

Type: Blazer LS, 4 x 4, 4-door SUV

Driver: 36-year-old female CDC: 12-FZEW-2, 12-LBAS-2

Veh. (B): 1995 Nissan

Type: Unknown model, passenger vehicle

Driver: 44-year-old female

CDC: 99-0000-0

Veh. (C): 1999 GMC

Type: Unknown model, pickup

Driver: 35-year-old male

CDC: 99-0000-0

SITUATION

(Slide 1) It was daylight, the sky was clear, and (slide 2) the five-lane, asphalt road surface was dry and free of defects. Case vehicle (A) was traveling south at an unknown speed in the center turn lane. Vehicle (B) had also been traveling south and was stopped in front of case vehicle (A) in the center turn lane. Vehicle (C) was traveling north in the left northbound lane. The driver of case vehicle (A) had undergone invitro fertilization earlier on the same day and this reportedly caused her to have a syncopal episode. As a result, case vehicle (A) drifted to the left and the driver failed to stop behind vehicle (B). The right front of case vehicle (A) struck the rear of vehicle (B). Case vehicle (A) then rotated clockwise, causing the left rear of the vehicle to enter the left northbound lane, where it was struck by vehicle (C). The drivers of case vehicle (A) and vehicle (B) were transported by ambulance to a regional level-one trauma center where they were treated and released. The driver of vehicle (C) did not sustain any injury.

GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slide 3) Overall damage to case vehicle (A) was moderate. (Slide 4) Direct damage to case vehicle (A) from the frontal impact began at the right-front bumper corner and extended 85 cm to the left, resulting in 56-percent vehicle overlap. The maximum crush from the frontal impact was 48 cm and occurred just to the right of the bumper center. (Slide 5) Direct damage to case vehicle (A) from the second impact began at the left-rear bumper corner and continued 77-cm forward. The maximum crush was 4 cm and occurred just forward of the rear taillight.

Using the WinSMASH accident-reconstruction program and (slides 6, 7, 8 and 9) a crush profile measured for case vehicle (A), the following impact severity was calculated for the frontal impact:

		Calculated Velocity Change - kph (mph)			
Vehicle	Variable	Total	Longitudinal	Latitudinal	
Case Vehicle (A)	EBS	35 (22)	-35 (-22)	-6 (-4)	

DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

Exterior

(Slide 10) In the front, the right headlight assembly, the grille, the hood, (slide 11) the right hood hinge, and the hood latch were damaged. The hood latch was jammed closed and was pried open by rescue or towing personnel. (Slide 12) The rear edge of the hood was elevated and it contacted the cowl, which contacted and cracked the windshield. (Slide 13) The right side of the engine compartment was crushed rearward.

On the left side, (slide 14) the rear quarter panel, the upper and lower sections of the D-pillar, and the gas tank cover were crushed inward, and the left-rear window was broken out. (Slides 15 and 16) There was no other left-side damage, and no significant change in the left wheelbase.

On the right side, (slide 17) the front fender, (slide 18) the upper and lower A-pillar, and (slide 19) the roof siderail were damaged. (Slide 20) There was no other right-side damage, but the right wheelbase was reduced 6 cm.

(Slide 21) In the rear, the left bumper corner and left taillight were damaged. There was no other damage to the rear of the vehicle.

Interior

This vehicle was equipped with steering-wheel and passenger frontal-impact airbags, and (slides 22, 23 and 24) both deployed during the frontal impact. (Slides 25 and 26) There was no damage to the steering-wheel or passenger airbag module covers. (Slide 27 and 28) There was no damage to the steering-wheel rim or (slide 29) spokes. There was no apparent horizontal or vertical displacement of the steering column. (Slides 30, 31, 32, 33, 34, 35, 36 and 37) There was no other interior damage and no measurable intrusions.

OCCUPANT KINEMATICS AND INJURIES

(Slide 38) The 5-ft, 9-in, 135-lb, 36-year-old female driver was wearing the three-point belt and the (slide 39) frontal-impact airbag deployed. (Slide 40) There was a small webbing imprint on the plastic D-ring, (slide 41) a webbing imprint on the plastic continuous loop, (slide 42) plastic transferred onto the belt webbing from the continuous loop, and (slide 43) the stitching of the energy-management loop was torn out, indicating belt use at the time of the crash.

On impact, the driver moved forward and slightly to the right relative to the vehicle interior, into the belt restraint and airbag. (Slide 44) There was lipstick and makeup transferred onto the airbag fabric just to the right of the circle of tether stitching. The driver sustained a contusion to her right knee, due to contact with the knee bolster, (slide 45) as evidenced by scuff marks on the knee bolster cover to the right of the steering column. She sustained a contusion across her abdomen, probably due to contact by the lap belt. (Slide 46) There were scuff marks on the knee bolster cover to the left of the steering column, but no injuries were reported from these potential contact points.

The following table and attached drawing (slide 47) summarize the injuries for the driver of case vehicle (A).

Occupant: Driver
Restraints: 3-point belt worn; frontal-impact airbag deployed

Age: 36 years
Stature: 175 cm (5 ft, 9 in)

Gender: Female


Mass: 61 kg (135 lb)

			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
Contusion, across abdomen	1 1		Lap belt	
Contusion, right knee	1		Knee bolster	
Maximum A.I.S. Level	1			
Injury Severity Score				
The second second	1			

Duplicate columns 1-8 from the previous card. Module G I Format 0 2 11 12		GENERAL INFORMATION	GI-1
TIME DATE OF COLLISION		ENVIRONMENTAL CONDITIONS CONSTRUCTION ZONE	
HOUR OF COLLISION	уу	(0) NO (1) YES (9) UNKNOWN	33
(24 HOUR CLOCK) 21 24		ROAD ALIGNMENT VERTICAL PLANE	
LOCATION STATE:		(1) LEVEL (2) CREST OF HILL (3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN	34
STATE FIPS CODE	25 26	ROAD ALIGNMENT HORIZONTAL PLANE	
AREA (1) URBAN (2) RURAL (9) UNKNOWN	27	(1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER:	35
ENVIRONMENTAL CONDITIONS		SURFACE COVERING	1,0
LIMITED-ACCESS HIGHWAY (0) NO (1) YES (9) UNKNOWN	<u>O</u> 28	(10) DRY (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	36 37
ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE) (1) 1-LANE (2) 2-LANES (3) 3-LANES (4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN	4 29	(31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN (41) ICE (51) SLUSH (61) SPILLED GRAVEL (71) OTHER: (99) UNKNOWN VISIBILITY LIMITATION	
INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR (8) NOT APPLICABLE •	8	(FOR CASE VEHICLE) (0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE (4) WINDSHIELD CONDITION	<u>O</u> 38
TYPE OF ROAD SURFACE (1) ASPHALT (2) CONCRETE (3) GRAVEL (4) MORE THAN ONE (CIRCLE EACH) (7) OTHER:	<u></u>	(5) GLARE (6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN VISIBILITY OBSTRUCTION (FOR CASE VEHICLE)	
(9) UNKNOWN ROAD DEFECTS (0) NO (1) YES (9) UNKNOWN	<u>Ø</u>	(0) NONE (1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE (9) UNKNOWN	39

GENERAL INFORMATION GI-			
ENVIRONMENTAL CONDITIONS SPEED LIMIT (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN	40	MECHANICAL MALFUNCTION WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE (0) NO (1) YES (2) YES, DID NOT CONTRIBUTE TO ACCIDENT (9) UNKNOWN	
PRECIPITATION	8 42 6 43	THE FOLLOWING SECTION SHOULD BE FILLED OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED. CIRCLE ITEMS INVOLVED. SUPPORT ANY ITEMS CIRCLED WITH COMMENTS. BRAKE SYSTEM DRIVER CONTROLS EXHAUST SYSTEM POWER TRAIN STEERING SYSTEM FUEL SYSTEM SUSPENSION SYSTEM VISIBILITY ITEMS ELECTRICAL SYSTEM TIRES THROTTLE CONTROLS UNKNOWN OTHER: COMMENTS:	
CROSSWIND (0) NONE (1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN LIGHT CONDITIONS (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN	44		

		GENERAL INFORMATION	GI-3
CRASH DETAILS CASE VEHICLE AND OBJECT (0) NO (1) YES (9) UNKNOWN	O 47	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE) (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL	
CASE VEHICLE ROLLOVER (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN	48	(5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	55
CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT) (0) NO (1) YES (9) UNKNOWN	<u>0</u>	DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	56
MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO (1) YES (9) UNKNOWN	50	DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	57
CASE VEHICLE AND CONTACTED STOPPED VEHICLE (0) NO (1) YES (9) UNKNOWN	51	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	55
STOPPED CASE VEHICLE AND CONTACTED VEHICLE (0) NO (1) YES (9) UNKNOWN	<u>O</u> 52	LIST IMPAIRMENTS MENTION	NED:
TOTAL NUMBER OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH (8) 8 OR MORE (9) UNKNOWN	<u>2</u>	Post - Crash Detail MANNER CASE VEHICLE LEFT SCENE	
ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE) (0) NO (1) YES (9) UNKNOWN	<u>∂</u> 54	(1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN (9) UNKNOWN	60



Duplicate columns 1-8 Module O V Format 0 4 from the previous card.	OTHER VEHICLE	OV-1	
MAKE: Nissan MODEL: Unknown passengen vehicle	CARGO:		
VIN			
MANUFAC/BODY CODE O 8 2 2 0 MAKE/MODEL CODE J 5 9 9 MODEL YEAR J 9 9 9 9 9 VEHICLE MASS (kg) 9 9 9 9 9 9 9 IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER O<	VEHICLE TYPE PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR (20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT (27) COMPACT (28) INTERMEDIATE (29) FULL MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107*, E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107*, E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (17) PICKUP CAR WITH CANOPY/SHELL COVER (21) MOTOR HOME (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (31) CHASSIS-MOUNTED CAMPER TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH SLIDE-IN CAMPER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (31) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH SLIDE-IN CAMPER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (33) UNKNOWN TRUCK TYPE (34) UNKNOWN TRUCK TYPE		
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	(33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S) BUS (40) UNKNOWN BUS TYPE (41) SCHOOL BUS (42) INTERCITY BUS (BETWEEN CITIES) (43) TRANSIT BUS (INTRACITY) (44) STREETCAR (ON TRACKS) (68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER) (99) UNKNOWN WHEELBASE (CTI) (999) UNKNOWN	<u>9 9 9</u> 58 59 60	

Duplicate columns 1-8 from the previous card. Module 0 V Format 0 2 11 12

OTHER VEHICLE

OV-2

ORIGINAL SPECIFICATIONS

Wheelbase

Front Overhang

 $\frac{9}{22} - \frac{9}{24}$ cm

Curb Weight

9999 kg

Rear Overhang

 $\frac{9}{25} \frac{9}{27} \frac{9}{27} \text{ cm}$

Average Track Width $\frac{9}{13} = \frac{9}{15}$ cm

Overall Length $\frac{9}{16} = \frac{9}{18} = \frac{9}{18}$ cm

Undeformed End Width (UEW) $\frac{9}{28} \cdot \frac{9}{9} \cdot \frac{9}{30}$ cm Engine Displacement $\frac{9}{31} \cdot \frac{9}{32}$ L

Overall Length

Overall Width (OAW) $\frac{9}{10} = \frac{9}{10}$ cm

Engine: # of Cylinders

VEHICLE DAMAGE

Not inspected

FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

 $\frac{9}{35} = \frac{9}{9} = \frac{9}{37} \text{ cm}$

Front-End Overlap (Percent) = DDL

99%

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)

99%

Duplicate columns 1-8 Module O V Format 0 11	4 12		OTHER VEHICLE	OV-1	
MAKE: GMC			CARGO:		
MODEL: UNKNOWN Pickup					
VIN					
MANUFAC/BODY CODE O 1 6 1	3	VEHICI	LE TYPE		
MAKE/MODEL CODE 309	9 30	(02) (03) (17)	GER VEHICLE LARGE LIMOUSINE PICKUP CAR UNKNOWN PASSENGER VEHICLE BODY	56	3
MODEL YEAR $\frac{1}{39}$ $\frac{9}{9}$	9 42	(24) (25) (26)	SUB-MINI		
VEHICLE MASS (kg) 9 9 9 9	9 48	(28) (29)	INTERMEDIATE FULL		
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	0	(14) \$ (15) I	IRPOSE PASSENGER VEHICLE SMALL UTILITY (WHEELBASE LESS THAN 107°, E.G. JEEP, BRONCO) LARGE UTILITY (WHEELBASE MORE THAN 107°, E.G. PANEL TRUCK, SUBURBAN)		
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	61	(17) F (21) F (22) F (23) F	PICKUP TRUCK WITH CANOPY/SHELL COVER PICKUP CAR WITH CANOPY/SHELL COVER MOTOR HOME PICKUP TRUCK WITH SLIDE-IN CAMPER PICKUP CAR WITH SLIDE-IN CAMPER CHASSIS-MOUNTED CAMPER		
TRAVELING SPEED (km/h) 9 9	9	TDUOK			
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	54	(13) L (15) L (16) F (22) F (30) L (31) C	VAN PICKUP TRUCK JINKNOWN LIGHT TRUCK ARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) PICKUP TRUCK WITH CANOPY/SHELL COVER PICKUP TRUCK WITH SLIDE-IN CAMPER JINKNOWN TRUCK TYPE CHASSIS-MOUNTED CAMPER DELIVERY VAN (WALK-IN)		
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE	0	(35) T (36) C (37) U (38) T	TRAIGHT TRUCK RUCK-TRACTOR (BOBTAIL) HASSIS-CAB INKNOWN HEAVY TRUCK RACTOR & SEMI-TRAILER (SEMI)		
(0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	55	BUS (40) U (41) S (42) IN (43) TI (44) S (68) TI (69) LC	RUCK (OR SEMI) & FULL TRAILER(S) NKNOWN BUS TYPE CHOOL BUS ITERCITY BUS (BETWEEN CITIES) RANSIT BUS (INTRACITY) TREETCAR (ON TRACKS) RAIN (CARS) DCOMOTIVE (ENGINE, SWITCHER)		
		WHEELE	BASE (cm)	999	
		(999) U	NKNOWN	58 59 60	

Duplicate columns 1-8 from the previous card. Module O V Format 0 2

OTHER VEHICLE

OV-2

ORIGINAL SPECIFICATIONS

Wheelbase

999 cm

Front Overhang

9 9 cm

Curb Weight

999 kg

Rear Overhang

 $\frac{9}{25} = \frac{9}{27} = cm$

Average Track Width $\frac{9}{13} \frac{9}{15}$ cm

$$\frac{9}{13} \frac{9}{15}$$
 cm

Undeformed End Width (UEW) $\frac{9}{28}$ $\frac{9}{30}$ cm

Engine Displacement

$$\frac{9}{31} \cdot \frac{9}{32}$$
 L

Overall Length $\frac{9}{16} = \frac{9}{18} = \frac{9}{18}$ cm Overall Width (OAW) $\frac{9}{19} = \frac{9}{21} = \frac{9}{21}$ cm

Engine: # of Cylinders

$$\frac{9}{33} \frac{4}{34}$$

VEHICLE DAMAGE

Not inspected

FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

$$\frac{9}{35} \frac{9}{9} \frac{9}{37}$$
 cm

Front-End Overlap (Percent) = DDL UEW

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW) OAW

Duplicate columns 1-8 Module V D Format 0 from the previous card.		VD-1
MAKE: Cheunolet MODEL: Blazen 4 x 4, 4-doon	SUY CARGO: Children toys me	vd
MODEL: 2142812 4 7 1 7 4000	100d 10 Kg	
VIN 13 G N D T 1 3	3 W 6 W Z	29
MANUFAC/BODY CODE $\frac{1}{30}$ $\frac{1}{3}$ $\frac{3}{3}$	STOLEN VEHICLE	
MAKE/MODEL CODE 293	(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	8 82
MODEL YEAR	8 42	
VEHICLE MASS (kg) 0 0 1 8 3 3	BODY STRUCTURE (1) BODY & FRAME	1
ODOMETER (km) 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	(2) UNITIZED (3) INTEGRAL-STUB FRAME (4) BODY & PLATFORM FRAME	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	(E.G. VW BUG) (5) PARTIALLY UNITIZED (7) OTHER: (9) UNKNOWN	
TRAVELING SPEED (km/h) 9 9 9	59	
(995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	TRANSMISSION (0) NONE (1) AUTOMATIC (2) MANUAL (9) UNKNOWN	<u></u>
VEHICLE TYPE		
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE 60	Z LOCATION OF TRANSMISSION SELECTOR LEVER	3
(12) 2-DOOR SEDAN OR COUPE (ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN	61 (1) FLOOR (2) CONSOLE (3) COLUMN (7) OTHER:	65
(15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH. : (19) PASSENGER VEHICLE, TYPE UNKNOWN	(9) UNKNOWN	
MULTIPURPOSE PASSENGER VEHICLE (21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO)	STEERING	,
(22) LARGE UTILITY (E.G. PANEL TRUCK SUBURBAN) (23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME	(1) POWER (2) MANUAL (9) UNKNOWN	66
TRUCK (31) PICKUP TRUCK, UNKNOWN	BRAKES	,
(32) PICKUP TRUCK, SMALL (DOWNSIZED) (33) PICKUP TRUCK, LARGE	(1) POWER (2) MANUAL (9) UNKNOWN	67
(99) UNKNOWN		

		VEHICLE DESCRIPTION VD-2	2
TYPE OF BRAKES (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	Z 68	WHEELBASE <i>(cm)</i> (999) Unknown	7 78
BRAKE ANTI-LOCK DEVICE (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN AIR CONDITIONING IN VEHICLE (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	2 69 70	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN	
TYPE OF DRIVE (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN	1 71	FIELD INVESTIGATOR INSTRUCTIONS: 1. INDICATE CRUSHED AREAS BY <u>OUT-LINING NEW PERIMETER</u> OF VEHICLE AND <u>SHADING THE DAMAGED AREAS</u> ON THE LARGE SKETCH ON PAGE VD-3. USE AS MANY SKETCHES AS NECESSARY TO COMMENT! VECCOME	
OUAL REAR WHEELS (0) NO (1) YES (9) UNKNOWN ORIGINAL TYPE OF RESTRAINT SYSTEM (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	<u>O</u> 72	TO COMPLETELY DESCRIBE THE DAMAGE. 2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE. 3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR. 4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:	
EQUIPPED WITH ROLL BAR (0) NO (1) YES (9) UNKNOWN TYPE OF ROOF (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	74 1 75	FRONT OR REAR ROOF (REFERENCE TO TOP OF DOOR SILL OR WINDOW SILL) SIDE	

Duplicate columns 1-8 from the previous card. Module V D Format 0 2

VEHICLE DESCRIPTION

VD-3

ORIGINAL SPECIFICATIONS

Wheelbase

Front Overhang

$${\color{red} \underline{O} \ \ {\color{red} \underline{S} \ \ {\color{red} \underline{S}} \ \ {\color{red} \underline{S}} \ \ {\color{red} \underline{C}} m}}$$

Curb Weight

Rear Overhang

$$\frac{1}{25} \frac{0}{0} \frac{6}{27} \text{ cm}$$

Average Track Width
$$\frac{1}{13} \frac{4}{4} \frac{2}{15}$$
 cm

Undeformed End Width (UEW) 1/28 5 0 cm

Overall Length

$$\frac{4}{16} \frac{6}{18} cm$$


Engine Displacement

$$\frac{4}{31} \cdot \frac{3}{32}$$

Overall Width (OAW) $\frac{1}{10}$ $\frac{7}{2}$ cm

Engine: # of Cylinders

VEHICLE DAMAGE



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A.

Front-End Overlap (Percent) = DDL UEW

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW) OAW

Duplicate columns 1-8 from the previous card. Module D A Format 0 2 11 12 DAMAGE DA-1						
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC				
EVENT NUMBER	13					
IMPACT SPEED (km/h)	9 4 4	9 9 9 35 36 37				
ESTIMATED BY	17	1 38				
CRUSH (cm)	$\frac{O}{18} \frac{4}{19} \frac{8}{20}$	$\frac{q}{39} \frac{q}{40} \frac{q}{41}$				
CDC #1	1 2 - F Z E W - 2	99.0000.0				
CDC #2	98.0000.0	<u>9</u> 9 . <u>0</u> <u>0</u> <u>0</u> . <u>0</u>				
Duplicate columns 1-8 Module D from the previous card. 9 1	A Format 0 3 0 11 12					
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC				
EVENT NUMBER	Z 13 Q Q G	a 4 6				
IMPACT SPEED (km/h)	14 15 16	$\frac{7}{35} \frac{l}{36} \frac{7}{37}$				
ESTIMATED BY	17	7 38				
CRUSH (cm)	$\frac{O}{18} \frac{O}{19} \frac{4}{20}$	$\frac{9}{39} \frac{9}{40} \frac{9}{41}$				
CDC #1	$\frac{1}{21} \frac{2}{2} \cdot \underline{L} \frac{B}{B} \frac{A}{A} \cdot \underline{S} \cdot \frac{2}{27}$	$\underline{9} \ \underline{9} . \underline{0} \ \underline{0} \ \underline{0} \ \underline{0} . \underline{0}$				
CDC #2	9 8.00000.0	99.000000 49				
Codes						
EVENT NUMBER	EVENT NUMBER IMPACT SPEED ESTIMATOR CRUSH					
(8) NOT APPLICABLI (9) UNKNOWN	(2) DRIVER	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE)				
IMPACT SPEED	(3) POLICE (4) "CRASH" PROGRAM (5) OTHER COMPUTER PROGRAM	(999) UNKNOWN CDC				
(998) NOT APPLICAE (999) UNKNOWN	BLE SPECIFY:	(9800000) NOT APPLICABLE (9900000) UNKNOWN				

Duplicate columns 1-8 from the previous card.

DAMAGE

DA-2

MAXIMUM SHEET METAL CRUSH

(cm) (999) UNKNOWN

FRONT
$$O 4 8$$

RIGHT SIDE O O O

LEFT SIDE <u>0</u> <u>9</u> <u>4</u>

OTHER <u>O</u> <u>O</u> <u>Ø</u> 30

CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE

NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER?

(0) NO (1) YES

EVENT NUMBER	IMPACT LOCATION (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE (3) ON ROADSIDE (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN	IMPACT CONFIGURATION FOR CODES, SEE TABLE ON PAGE DA-3.	OBJECT/VEHICLE CONTACTED FOR CODES, SEE TABLE ON PAGE DA-4.
# 1	1 32	<u>/ 4</u>	2 <u>0</u>
#2 .	1 37	26 39	13/41
#3	42		46
#4	47	49	
#5	52	 	
#6	 57	<u></u> 59	
#7	62	64	66
L			

CODES FOR IMPACT CONFIGURATION

FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND <u>UNKNOWN</u> OTHER VEHICLE CONFIGURATION

LEFT SIDE OF CASE VEHICLE

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

REAR OF CASE VEHICLE

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

RIGHT SIDE OF CASE VEHICLE

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

UNKNOWN

(99) IMPACT TYPE UNKNOWN

CODES FOR VEHICLE/OBJECT CONTACTED

VEHICLE/OBJECT GROUPS

- NO OBJECT
- (00) NO OBJECT (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT
- (98)OTHER (DESCRIBE)
- UNKNOWN (99)

PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

SIZE

WHEELBASE

MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
- (12) PICKUP
- (14) SMALL UTILITY (WHEELBASE LESS THAN 107°, E.G. JEEP, BRONCO)
- (15) LARGE UTILITY (WHEELBASE MORE THAN 107". E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (17) PICKUP CAR WITH CANOPY/SHELL COVER
- (21) MOTOR HOME
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (23) PICKUP CAR WITH SLIDE-IN CAMPER
- (31) CHASSIS-MOUNTED CAMPER

TRUCK

- (11) SMALL VAN (E.G. ECONOLINE)
- (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER

- (31) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

BUS

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

MOTORCYCLE

- (50) UNKNOWN MOTORCYCLE TYPE
- (51) 1 75 cc (52) 76 125 cc (53) 126 250 cc

- (54) 251 500 cc (55) 501 - 750 cc
- (56) 751 cc +
- (57) 3-WHEELS (OR WITH SIDECAR)

SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE)
- (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE
- (66) TRAILER, PRIVATE (CAMPER)
- (67) TRAILER, COMMERCIAL (CARGO)
- (68) TRAIN (CARS)
- (69) LOCOMOTIVE (ENGINE, SWITCHER)

OBJECT

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE, ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT
- (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT
- (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL
- (90) GUARD RAIL, LEADING SECTION (91) GUARD RAIL, MIDDLE OR UNKNOWN
- (92) GUARD RAIL, TRAILING SECTION
- (93) GUARD POST (TIMBER, METAL, CONCRETE)
- (94) CABLE, FENCE BARRIER
- (95) CONCRETE BARRIER (MEDIAN)
- (96) IMPACT ATTENUATOR
- (97) BREAKAWAY FEATURES

	R Format 0 1 12		SH RECONSTRUC or AV	CTION CR-1
		PRIMARY IMPACT	CASE VEHICLE SE	ECONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13	veh (B)	<u>Z</u>	veh (c)
ΔV (km/h) TOTAL	14 = 15 16	$\frac{9}{32} \frac{}{33} \frac{}{34}$	48 49 50	9 —
LONGITUDINAL*	17	35 38	9	69
LATERAL*	9	9	9	9
NOTE: THESE ΔV COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76
EXAMPLES: 10 km/h = ± <u>Q 1 Q</u> -7 km/h = <u>: Q Q 7</u>				
ENERGY DISSIPATED BY CRUSH (kg)	9	9	$\frac{g}{59}$ ${}$ ${62}$	<u>q</u>
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	12		08	
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE				
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	<u>5</u>		5 65	
COMPUTER PROGRAM SPECIFY:				

Duplicate columns 1-8 from the previous card.

CRASH RECONSTRUCTION for FRS

CR-2

from the previous card.	for EBS			
	<u> </u>	PRIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13	Veh (B)	<u>Z</u>	veh(c)
EBS (km/h) TOTAL	0 3 5	32 33 34	48 49 50	<u>9</u>
LONGITUDINAL	$\frac{-035}{17}$	35 38	$\frac{9}{51} = {54}$	$\frac{9}{69} = \frac{72}{72}$
LATERAL* *NOTE: THESE EBS COMPONEN MUST INCLUDE SIGN. EXAMPLES: 10 km/h = ± 0 1 0 -7 km/h = ± 0 0 7	TS = 0 0 6 24	39 42	55 58	73 76
ENERGY DISSIPATED BY CRUSH (kj)	$\frac{\mathcal{O}}{25} \stackrel{\mathcal{O}}{=} \frac{\mathcal{Q}}{28}$	43 46	$\frac{9}{59}$ ${}$ ${62}$	9
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOW CONFIDENCE LEVEL (21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERA CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL NOT RECONSTRUCTED BECAUSE (02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED	29 30		<u>O</u> <u>8</u> 64	
MODE (1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED COMPUTER PROGRAM SPECIFY: WINSMASH	31		<u>5</u> 65	

Duplicate columns 1-8 from the previous card.

CRASH RECONSTRUCTION

CR-3

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C $_1$ TO C $_6$ FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.

CASE VEHICLE

LOCATOR


- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L
	65 cm vadamaged At ALLA BC	Front Dumpen BC to BC
2	Begin U. arms BC -77cm forward	Same
	(d) (2) (d) (d) (d) (d) (d) (d) (d) (d) (d) (d	UEN = 150
	C6 C5	¢₁ ¢₁



- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other
- (9) Unknown



UDL 65°

CRUSH PROFILE IN CENTIMETERS

2	ų	077	004	077	999	999	99	999	949	999	+999
	7										
2	(I	77	u	77	24 25 26	27 20 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 4
1	<i>J</i>	085	0 48	135	000	00Z	OZ1	048	043	044	
			-2		-17	-9	-2	-2	-9	ツ フ	
	1	85	50	135	9	11	23	50	52	61	+43
Impact Number	of Impact C-Measur.	Length (DDL)	Max Crush	Field	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
Specific	NOTE: Eacl	h line in the ta	ble below is a t Damage	separate rec	ord (card).	Dt.	uplicate col	umns 1 -	12 for each	complete	d line.

Duplicate columns 1-8
from the previous card.

CRASH RECONSTRUCTION

CR-4

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C $_{\rm 1}$ TO C $_{\rm 6}$ FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.


OTHER VEHICLE

LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L



DL _____

UDL _____

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other _
- (9) Unknown

CRUSH PROFILE IN CENTIMETERS

	NOTE: Each	line in the tab	le below is a	1 PHOFILE separate rec	ord (card).		plicate col	umns 1 - 1	2 for each	complete	d line
Specific Impact Number	Plane of Impact C-Measur.	Direct Length (DDL)	Damage Max Crush	Field L	C ₁	C ₂	c ₃	C ₄	C ₅	C ₆	±D
1											
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
2											

Duplicate columns 1-8 from the previous card. Module W T 9 10	Format 0	1 12	WHEELS AND TIRES WT-1
WHEELSDAMAGED (0) NO (1) YES (9) UNKNOWN	LF RF RR LR	0 13 0 0 0 0	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S) LF
TIRE TREAD TYPE (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF RF RR LR	4 17 4 4 20	LR ¥
CARCASS CONSTRUCTION (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF RF RR LR	3 3 3 3 24	
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:			

Duplicate columns 1-8 Module F T Format from the previous card. 9 10	0 1	FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	21
MAIN TANK LOCATION	322 14 16	AUXILIARY TANK LOCATION	88 X 22 24
MAIN FILLER CAP LOCATION	17 1 3	AUXILIARY FILLER CAP LOCATION	888 25 27
MAIN TANK MATERIAL	3 20	AUXILIARY TANK MATERIAL	§ 28

TANK AND FILLER CAP LOCATION CODES

FIRST DIGIT (LONGITUDINAL)

- (1) BEHIND KICK-UP
- (2) IN KICK-UP
- (3) BETWEEN KICK-UP & COWL
- (4) FORWARD OF COWL
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

SECOND DIGIT (LATERAL)

- (1) LEFT OF FRAME
- (2) WITHIN FRAME OR CENTERED (3) RIGHT OF FRAME
- (4) DUAL, RIGHT & LEFT TANKS
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

THIRD DIGIT (VERTICAL)

- (1) BELOW FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) ABOVE FRAME
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

TANK MATERIAL CODES

- (1) STEEL
- (2) ALUMINUM
- (3) PLASTIC
- (7) OTHER
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

Duplicate columns 1-8
from the previous card.

Module <u>F</u> <u>L</u> Format <u>0</u> <u>1</u> 12

FUEL LEAKAGE

FL-1

DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.

(1) YES COMPLETE PAGE.

0

	1	11	111	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15	<u> </u>	_			21
#2	22 23	_				29
#3	30 31	_				37
#4	38 39					45
#5	46 47					53

LEAKING COMPONENT

TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP)
- (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP) (19) TANK AREA, DETAILS UNKNOWN

DELIVERY SYSTEM

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO CARBURETOR OR INJECTOR PUMP)
- (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

EEC SYSTEM (CONTINUED)

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT, COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

II COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

V LOCATION OF LEAK

FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P, BETWEEN COWL & REAR BULKHEAD
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

SECOND DIGIT (LATERAL LOCATION)

- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format (from the previous card. 9 10 1	<u>1</u> 12	FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP</u> PAG (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.

Duplicate columns 1-8 Module E D Format from the previous card.	0 1 12	Exterior Damage	ED-1
HOOD PERFORMANCE FOR THE FOLLOWING, USE CODES: (0) NO (1) YES (8) NOT APPLICABLE		STEERING COL FLEXIBLE COUPLING FLEXIBLE COUPLING TYPE (0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT	9 26
(9) UNKNOWN HOOD LATCH(ES)RELEASED	13	(4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OTHER: (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED	
Pried 9 - JAMMED	14 15	COUPLINGDAMAGED (USE CODES FROM HOOD PERFORMANCE) -SEPARATED (COMPLETE)	9 27 9 28
HOOD HINGESLEFT, DAMAGED -LEFT, SEPARATED (COMPLETE)	16 0 17		
-RIGHT, DAMAGED -RIGHT, SEPARATED (COMPLETE)	18 0 19	ENG COMPART TELESCOPING UNIT TYPE OF UNIT (00) NONE INSTALLED	8 8
HOOD REMAINED ON VEHICLE	<u>l</u>	(01) - (07) SEE UNITS ON PAGE ED-2 (88) NOT COLLECTED (97) OTHER:	29 30
REAR EDGE OF HOODELEVATED -CONTACTED WINDSHIELD -PENETRATED WINDSHIELD	21 0 22 9 23	ORIGINAL LENGTH (mm) F (OR H): TELESCOPED LENGTH (mm) G:	
HOOD LATCH LOCATION		G	
(1) FRONT OF VEHICLE (2) COWL AREA (3) SIDE (8) NOT APPLICABLE (9) UNKNOWN	7 24	DIFFERENCE (mm) F (OR H) - G (IF LESS THAN 15mm, ENTER *000*.)	
ENGINE OR TRANSMISSION MOUNT SEPARATION (COMPLETE) (0) NO (1) YES (9) UNKNOWN	$\frac{\mathcal{J}}{25}$	(888) NOT COLLECTED (991) NOT MEASURED/NO COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 33

		EXTERIOR DAMAGE	i	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u>	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION?		
LEFT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		USE CODES: (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN		
-A-PILLAR, UPPER	<u>0</u>	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	DONT	٥
LOWER	O 36		REAR	43
-B-PILLAR, UPPER	<u>O</u> 37	DOORS JAMMED CLOSED-		
LOWER	$\frac{\mathcal{D}}{38}$	USE CODES: (0) NO (1) YES		
-C-PILLAR, UPPER	<u>O</u> 39	(8) NOT APPLICABLE <i>(NO DOOR)</i> (9) UNKNOWN	PONT	0
LOWER	0 40		RONT	O 45
-D-PILLAR, UPPER	<u>O</u>			46
LOWER	42			

	OTHER REAR DAMAGE	
	WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION?	G
$\frac{2}{47}$	(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	50
	SPARE TIRE	8
	(1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (8) NOT COLLECTED	51
	(9) UNKNOWN	
	TRAILER HITCH TYPE (0) NO HITCH	^
	BALL-AND-SOCKET TYPES (1) TEMPORARY FRAMEWORK (F.G.	52
	RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON-EQUALIZING)	
	OTHER TYPES	
	(5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL. P/U) (7) OTHER (E.G. CLEVIS-AND-PIN)	
<u>O</u>	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED	
	TRAILER TYPE (AT TIME OF COLLISION) (0) NO TRAILER	5
	(1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) LITH ITY TRAILER	53
	(5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN	
<u>D</u>	(9) UNKNOWN	
	<u>D</u>	(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN SPARE TIRE (0) NO SPARE TIRE (1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (8) NOT COLLECTED (9) UNKNOWN TRAILER HITCH TYPE (0) NO HITCH BALL-AND-SOCKET TYPES (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON- EQUALIZING) (4) LOAD EQUALIZING OTHER TYPES (5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL PU) (7) OTHER (E.G. CLEVIS-AND-PIN) (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED TRAILER TYPE (AT TIME OF COLLISION) (0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN (9) UNKNOWN

		EXTERIOR DAMAGE	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	Q 54	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES:	
RIGHT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN OPENED BECAUSE OF (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER LOWER -B-PILLAR, UPPER	<u>4</u> 55 <u>4</u> 56 <u>O</u>	(98) NOT APPLICABLE <i>(NO DOOR)</i> (99) UNKNOWN -FRONT -REAR	0 0 63 64 0 0 65 66
LOWER -C-PILLAR, UPPER	57 O 58 O 59	DOORS JAMMED CLOSED- USE CODES: (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	
LOWER -D-PILLAR, UPPER	Q 60 Q 61	-FRONT	9 67 9 68
LOWER	<u>O</u> 62	VAN REAR DOOR TYPE (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	8


		EXTERIOR DAMAGE	ED-5
WINDSHIELD DAMAGE WINDSHIELD CRACKED		WINDSHIELD MARK ON CASE VI	EHICLE
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	70	SHADED SOLAR-RAY	
WINDSHIELD BROKEN (PLASTIC INTERLAYER TORN) (0) NO	<u>O</u>	SAFETY LOF SAFETY AS-1	:
(1) YES (8) NOT APPLICABLE (9) UNKNOWN	71	LAMINATED C 1 DOT15 M10	
CRACKED OR BROKEN BY OCCUPANT CONTACT (0) NO (1) YES (8) NOT APPLICABLE	<u>O</u> 72	WINDSHIELD CODE	
(9) UNKNOWN EXTENT OF BOND SEPARATION		(97) DESCRIBED BUT NOT CODED (98) NOT APPLICABLE (NO WINDSHIELD) (99) UNKNOWN	T 2 75
(0) NONE (1) 1 - 20% (2) 21 - 40 (3) 41 - 60 (4) 61 - 80 (5) 81 - 99	73	ROOF DID T-ROOF/SUN ROOF OPEN DURING COLLISION?	
(6) TOTAL (7) SEPARATED, AMOUNT UNKNOWN (8) NOT APPLICABLE (9) UNKNOWN		(0) NO (1) YES (8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF) (9) UNKNOWN	76
LOCATE AREA OF WINDSHIELD IN & HORIZONTAL) ON THIS DIAGRA	TEREST O	R DAMAGE WITH DIMENSIONS (VERTICAL WINDSHIELD AS VIEWED FROM INSIDE.	
		Cracked by cowl contact	
L	_	_	R

Duplicate columns 1-8 Module S C Format 0 from the previous card. 9 10 11		STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL		STEERING WHEEL POSITION AT TIME OF COLLISION	
STEERING WHEEL RIM DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	13	IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED? EXAMPLES O'CLOCK = 1 2 O'CLOCK = 0 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	4	(NORMAL STRAIGHT AHEAD) O'CLOCK = 1	
STEERING WHL SPOKE DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE (1) EXAMPLES: BARRACUDA, 70 - 74 CHALLENGER, 70 - 74 CAPRI, 71 - 77	
STEERING COLUMN OPTIONS		(2) EXAMPLES: OMNI, 78 - HORIZON, 78 -	
TILT FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	3	TYPE OF DEVICE (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED	8 19
SWING-AWAY FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>0</u>	ORIGINAL DIMENSION (mm) A: DAMAGE DIMENSION (mm) B: DIFFERENCE (mm)	
TELESCOPING FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>O</u> 18	A - B (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 22

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN ENERGY ABSORBING DEVICE		STEERING WHEEL (CONTINUED)	
TYPE OF DEVICE * (IF 27 OR 28)		OTERDING WHEEL LIND DAMAGE	
(00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8 24	STEERING WHEEL HUB DAMAGE (0) NONE (1) OCCUPANT CONTACT (2) AIRBAG (3) OTHER	<u>Q</u>
ORIGINAL LENGTH (mm)		(9) UNKNOWN	
C:			
COMPRESSED LENGTH (mm)			
D:			
BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE) OR			
COMPRESSION (OR EXTRUSION) (mm)			
C - D (OR E) (TOLERANCE: ±10)			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 27		
* (ADD A & B FOR TOTAL COMPRESSION)			
SHEAR CAPSULE SEPARATION (mm)			
S (USE AVG. OF LEFT & RIGHT CAPSULES.)			
LT:			
RT:			
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 30		
COLUMN VERTICAL ROTATION			
(0) NO APPARENT ROTATION(1) UPWARD APPARENT ROTATION(2) DOWNWARD APPARENT ROTATION(9) UNKNOWN	<u>O</u> 31		
COLUMN LATERAL ROTATION			
(0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	<u>32</u>		

					Intrus	SION IT-1
					(All Measurements Are in Centimeters)	
Location Intrusion	of 1	Intruded	Component	Compari Value	Dominant Crush Direction	
					_ =	
					_ =	
					= =	
					- =	
					_ =	
					- =	
					= =	
					_ =	
	-				_ =	
					- =	
					_ =	
					- =	
					_ =	
					_ =	
			C	CCUPANT C	ONTACT WORKSHEET	
Contact	C	Interior omponent ontacted	Occupant No. if Known	Body Region if Known	Supporting Physical Evidence	Confidence Level of Contact Point
Α	K	vec bolden	Pn	Lt. KNET	Scuttmark	,
В		//	11	u	0	,
С		//	/1	Rt. KNES	14	,
D		11	И	11	/)	/
E						
F						
G						
Н						
ı						
J						

VEHICLE OCCUPANT CONTACT DIAGRAM



CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.


(1) LEFT	(3) RIGHT		INDIVIDUAL SEAT
(1) LEFT	(2) CENTER	(3) RIGHT	BENCH: FULL WIDTH 3 PASSENGER
(1) LEFT	(2) LEFT CENTER	(6) RIGHT (3) RIGHT CENTER	BENCH: FULL WIDTH 4 PASSENGER
(1) LEFT	(2) CENTER	(5) RIGHT &AISLE SPACE	BENCH: PARTIAL WIDTH, LEFT
((D) LEFT & SPACE	(2) CENTER	(5) RIGHT &SPACE	BENCH: PARTIAL WIDTH, CENTERED
(4	4) ENTIRE	VEHICLE WIDTH		. CARGO AREA

EXAMPLES

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.



VAN 12 PASSENGER CAPACITY



CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT	INJURY	
NUMBER	NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(99)	(00) OR (99)	UNKNOWN IF CONTACT

CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

INDIVIDUAL COMPONENT

INTERNAL

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE
- (18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (22) BACK PANEL/BACK DOOR SURFACE
- (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

EXTERNAL

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE
- (46) OTHER (E.G. SPARE TIRE, JACK. DÈSCRIBE.)
- (49) UNKNOWN EXTERNAL OBJECT

GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF ALL THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

(50)WINDSHIELD HEADER

A-PILLAR

ROOF SIDE RAIL

- (51)INSTRUMENT PANEL A-PILLAR DOOR PANEL
- (52)INSTRUMENT PANEL

A-PILLAR

WINDSHIELD HEADER

(53)DOOR PANEL **B-PILLAR**

ROOF RAIL

(54)DOOR PANEL A-PILLAR

ROOF RAIL

(55)INSTRUMENT PANEL

FLOOR PAN A-PILLAR

DOOR FRAME

(56)ROOF RAIL

A-PILLAR

B-PILLAR WINDOW FRAME

(57)ROOF RAIL

A-PILLAR

B-PILLAR

C-PILLAR

DOOR PANEL

(58)ROOF

ROOF RAIL

WINDOW FRAME

DOOR PANEL

(59)BACKLIGHT HEADER

ROOF

C-PILLAR

THIRD SEAT-BACK

(60)ROOF **ROOF RAIL**

A-PILLAR

B-PILLAR

C-PILLAR

WINDOW FRAME

DOOR PANEL FLOOR PAN

(61)INSTRUMENT PANEL

TOE PAN

WINDSHIELD HEADER

A-PILLAR

ROOF RAIL

WINDOW FRAME DOOR PANEL

ROOF

(62)ROOF

ROOF RAIL

C-PILLAR

WINDOW FRAME

FLOOR PAN

SECOND SEAT

DOOR PANEL

(63)ROOF RAIL

ROOF

B-PILLAR

WINDOW FRAME

FLOOR PAN

DOOR PANEL

SECOND SEAT

FRONT SEAT

(64)ROOF RAIL

ROOF OR CONVERTIBLE TOP

A-PILLAR **B-PILLAR**

WINDOW FRAME

WINDOW HEADER

(65)WINDSHIELD

WINDSHIELD HEADER

ROOF SIDE RAIL

(66)WINDSHIELD WINDSHIELD HEADER

A-PILLAR

(98)NOT APPLICABLE

(99)UNKNOWN

Duplicate columns 1-8 Module from the previous card.	1 T Format 0 1 9 10 11 12			Inte	RUSION	IT-5
WAS THERE OCCUPANT COM (0) NO <u>DO NOT</u> ANSWER NEX (1) YES <u>ANSWER</u> NEXT QUEST (9) UNKNOWN <u>SKIP PAGE</u>	T QUESTION. SKIP PAGE.	<u>O</u> 13	VAS INTRUSIOI (0) NO <u>CO</u> (1) YES <u>SK</u>	MPLETE PA		14
Duplicate columns 1-8 Module from the previous card. NOTE: Each line in the table below	I T Format 0 2 9 10 11 12 is a separate record (card). Du	plicate column	s 1 - 12 for each c	ompleted li	ne.	
CODES F	TRUSIONS IN THIS ORDER: LE FOR B, F, G, H, I, J ON PAGE FOR C ON PAGE IT-4	FT TO RIGHT IT-3	ON ROW; FRON			'S.
	D E F ASSOC. MAXIMUM MAXIMUM EVENT INTRUSION INTRUSION NO. X AXIS (cm) Y AXIS (cm)			I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14 15-16 17-18	19 20-21 22-23	24-25	26-27	28-29	30-31	32-33
	AN 7 INTRUSIONS. T Format 0 3 9 10 11 12	 				
SIDE DOOR INTRUSION RESULTED FROM INTRUSION NUMBER CAUSE CODES FOR CAUSE: 13 15 (1) DIRECT IMPACT 16 18 (2) INDUCED DAMAGE 19 21 (9) UNKNOWN		DOOR CO ION, CODE DAMAGED DMPONENT 1	DAMAGE COMPONEN 25 29 33	T D NT 2 F (0 (1 (2 (3 (4 (5)	CODES COR COMPONE O) NONE 1) A-PILLAR 2) B-PILLAR 3) C-PILLAR 4) LATCH/STRII 5) HINGES 7) OTHER: 1) NOT APPLIC 1) UNKNOWN	NTS KER

Duplicate columns 1-8 from the previous card.

Module <u>I</u> <u>T</u> Format <u>0</u> <u>2</u> 12

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

- ADDITIONAL PAGE --

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES.

CODES FOR B, F, G, H, I, J ON PAGE IT-3

CODES FOR C ON PAGE IT-4

OCCUPANT CONTACT AND INJURY

A INTRUSION NUMBER	B OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT			F MAXIMUM INTRUSION Y AXIS (cm)		H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8			_							
0 9			_							
1 0										
11			_							
1 2				— —						
1 3			_							
1 4										
<u>1</u> 5			_							
<u>1</u> 6										
<u>1</u> <u>7</u>										
1 8										
<u>1</u> 9										
<u>2</u>										
2 1			_							
2 2			_							
2 3			_							
24										
<u>2</u> <u>5</u>			•				<u> </u>			


Duplicate columns 1-8 from the previous card.	Modu	ile <u>I</u> D	Format 0 1		ln	TERIOR DAMAGE	D-1
co	(1	O) NO I) YES B) NO, and	d OCCUPANT CONTACT	(8) N	ES, and C OT APPL	DCCUPANT CONTACT ICABLE I	
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR C-PILLAR D-PILLAR HEADLINING ROOF STRUCTURE T-ROOF/SUN ROOF OTHER: *	LEFT O 13 O 15 O 17 O 19 O 21 O 23 O 25 O 27 O 29 O 31 O 35 O 35 O 35 O 39 & 41 & 43	RIGHT Q14 Q16 Q18 Q20 Q12 Q14 Q16 Q18 Q30 Q34 Q34 Q34 Q34 Q34 Q34 Q34 Q44 X5 Q42 X5 Q44 X5 Q	FRONT FOOT CONTROLS IGNITION KEYS REAR VIEW MIRROR SUNVISOR/FITTINGS (5) LEFT SIDE ONLY (6) RIGHT SIDE ONLY (7) BOTH SIDES WINDSHIELD TOP MOLDINGS LEFT A-PILLAR (UPPER OR LOWER) RIGHT A-PILLAR (UPPER OR LOWER) CENTER CONSOLE TRANSMISSION SELECTOR LEVER RIM, HORN, SPOKE		O 45 O 46 O 47 O 48 O 50 O 51 O 52 O 53 O 54	INSTRUMENT PANEL UPPER PANEL MID PANEL LOWER PANEL ASHTRAY CONTROL KNOBS & LEVERS GLOVE COMPARTMENT AREA INSTRUMENTS PARKING BRAKE RELEASE PARKING BRAKE PEDAL A/C OR UPPER VENT OUTLETS HEATER OR A/C DUCTS RADIO OTHER: * REAR WINDOW WINDOW HEADER CONSOLES VERTICAL	64 Q 65 Q 66 Q 67 Q 68 Q 69
						ROOF	70 0 71

^{*} MORE THAN ONE ITEM MAY BE NOTED.

Duplicate columns 1-8 Module S T from the previous card. 9 10			SEATS	;	ST-1
FRONT SEAT TYPE OF FRONT SEAT (00) NO SEAT	DRIVER	Passen'r	FRONT SEAT-BACK	DRIVER	PASSENT
(00) NO SEAT (01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE (04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE (09) INDIV. BENCH, PASS. WIDE	0 5	<u>O</u> <u>J</u>	SEAT-BACK TYPE (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	3/30	3 31
(97) OTHER:	17		SEAT-BACK LOCK TYPE (0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u>	20	LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE	34	35
ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	1 21		(9) UNKNOWN RECLINER MECHANISM HELD (0) NO	1	<u>_l</u>
CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u> 23	<u>\$</u>	(1) YES (8) NOT APPLICABLE (9) UNKNOWN	36	37
FRONT SEAT DAMAGE (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	<u>0</u> 25	<u>6</u> 26	HEAD RESTRAINT HEAD RESTRAINT TYPE (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	<u>Z</u>	2
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	1 5c R#	hod .	(9) UNKNOWN REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Q</u> 40	<u>O</u>
FRONT SEAT ROTATION (0) NONE APPARENT	<u>O</u> 28	0	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN	8 42	<u>\$</u>
(1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	28	29	HEAD RESTRAINT DAMAGE (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	<u>ð</u>	<u>ð</u>

			Si	EATS	ST-2
FRONT SEAT ADJUSTMENT SEAT ADJUSTMENT TYPE	DRIVER	PASSEN'R	SECOND SEAT (CONT.)		
(0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN	2/46	1/47	CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE	_	<u>8</u>
ADJUSTMENT PROVIDED (1) 2-WAY (2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	3	49	(9) UNKNOWN IF EQUIPPED SECOND SEAT-BACK LOCKS	LEFT	Rіgнт
(9) ONKNOWN SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u> 50	<u>O</u>	FOR THE FOLLOWING, USE: (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN		
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN	52	53	LEFT OR CENTER, EQUIPPED LEFT OR CENTER, HELD (3) SEAT FOLDED DOWN RIGHT, EQUIPPED	61 1 63 0	0 820 4 748
PRE-CRASH POSITION (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	<u>3</u>	<u>Z</u>	RIGHT, HELD (3) SEAT FOLDED DOWN THIRD SEAT	67	<u>3</u> 68
SECOND SEAT	LEFT	Right	EQUIPPED	<u>O</u>	<u>O</u>
TYPE OF SECOND SEAT (0) NONE (1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT (5) INTEGRAL CHILD SEAT	<u>2</u>	2	BACKREST DAMAGED CUSHION DAMAGED	8 71 8 73	\frac{\frac{7}{72}}{2}
(6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	<u>0</u> 58	O 59	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN Applies to any rear-seat position	7	5

Duplicate columns 1-8 Module A B Format 0 from the previous card.		AIRBAG	AB-1
DRIVER SIDE LOCATION OF AIRBAG		PASSENGER SIDE	
STEERING WHEEL		INSTRUMENT PANEL (GLOVE BOX)	
EQUIPPED		EQUIPPED	
(0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	13	(0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	16
DEPLOYED		DEPLOYED	
(0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	14	(0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	17
CONDITION OF AIRBAG		CONDITION OF AIRBAG	
STEERING WHEEL		INSTRUMENT PANEL (GLOVE BOX)	
(0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPEDINOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	<u>O</u>	(0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED/NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	18
DRIVER SIDE		PASSENGER SIDE	
AIRBAG		AIRBAG	
STEERING WHEEL		INSTRUMENT PANEL (GLOVE BOX) TETHER	
(0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	(0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	21
MARKED BY CONTACT		MARKED BY CONTACT	
(0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	20	(0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	22



NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,
OCCUPANT INFORMATION AND INJURY CLASSIFICATION,
ARE TO BE FILLED IN
FOR EACH CASE VEHICLE OCCUPANT,
WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 Module O C Format C from the previous card.) <u>2</u> 1 12	Occupant Information	OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER ROLE OF OCCUPANT AT 1ST IMPACT (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	13 14 15	PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN MASS (kg)	3 6 20 21 2 5 22 23
OCCUPANT POSITION ROW LOCATION (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	(999) UNKNOWN (135/6) HEIGHT (cm) (999) UNKNOWN (5ft, 9in) SEX (1) MALE (2) FEMALE (9) UNKNOWN	$ \begin{array}{c c} 0 & 6 & 1 \\ \hline 24 & 25 & 26 \end{array} $ $ \begin{array}{c c} 1 & 7 & 5 \\ \hline 27 & 28 & 29 \end{array} $ $ \begin{array}{c c} 2 & 30 \end{array} $
LATERAL LOCATION (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN POSTURE	17	MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA (07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD WITHIN 27	<u>O</u> <u>Z</u> 31 32
(10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER: (99) UNKNOWN	18 19	(09) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH NON-FATAL INJURY (7) OTHER: 100-VITAD FERTIZATION (8) COMBINATION OF ABOVE BEFORE (CIRCLE EACH) (9) UNKNOWN	<u>0</u> <u>1</u> <u>33</u> 2 <u>7</u> <u>35</u>


		OCCUPANT INFORMATION	OC-2
MEDICAL CONDITIONS (CONT.) POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	36	CHILD SEAT TYPE (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	8 41
ACTIVE RESTRAINT SYSTEM (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS	3 37 38	EJECTION DEGREE OF EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, RIGHT SIDE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	9 4 4
(3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN PASSIVE RESTRAINT SYSTEM USAGE (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	2 40	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	1 46

OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (B) NOT APPLICABLE (9) UNKNOWN OCCUPANT INFORMATION SOURCE OF INFORMATION (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN

OCCUPANT INFORMATION OC-4

INDICATE LOCATION OF INJURIES.





Duplicate columns 1-8 from the previous card.

Module I C Format 0 1 12

Injury Classification IC-1

NOTE: Each line in the table below is a separate record (card).


Duplicate columns 1 - 12 for each completed line.

OCCUPANT INJURY CLASSIFICATION

		_				PRIM	IARY	OIC		A	ssoc	IATE	OIC		COMMENTS			
OCCUPANT NUMBER	INJURY NUMBER	PROBAL START V IN 1ST C	BILITY (HORI WITH MOST CONTACT AF	N ORDER OF ZONTALLY) . PROBABLE REA COLUMN. LE CONTACT	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 45	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY US				
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	-			
01	01	34			M	W	<u>८</u>	I	1	_		_	_					
1	02	<u>56</u>			K	<u>R</u>	<u>८</u>	Ţ	1	_				_				
					-	_	_	_	-	_				_				
					-				_	_	_			_				
			1		-	_	_		-	_	_		*******					
					_				-	_			_	-				
					_				-	_				-				
e e					-	_		_	-	-		—	_	_				
					_				-	_		_	_					
Mumber					-	_	_	_	-	_				-				
ccupam					-	_	_	_	-	<u>-</u> -	_		_	-				
Dupilicate Occupant Number Toreach line.					_	_			-	_	_		_	-				
3					_	_	_		-	-	 .			-				
						_		_	-					-				
					_	_		_	-	-			_	-				
					_		_			_			_	-				
					_		_			_			_	-				
					`	_	_	_	-	_		_						

CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

FRONT	OF PASSENGER COMPARTMENT	SIDES	
(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING	(20)	SURFACE OF SIDE INTERIOR
(12)	WINDSHIELD	(19)	
(- /		(13)	
(05)	INSTRUMENT PANEL (SPECIFIC AREA UNKNOWN)	(24)	
(54)	UPPER INSTRUMENT PANEL (X)	(24)	COATTIOOK
(55)	MIDDLE INSTRUMENT PANEL (Y)	(22)	WINDOW GLASS (SIDE)
(56)	LOWER INSTRUMENT PANEL (Z)	• •	· · ·
	• •	(21)	WINDOW FRAMES (SIDE)
(81)	ASH TRAY (INSTRUMENT PANEL)	(00)	DOOF OIDE DAIL
(02)	GLOVE COMPARTMENT AREA	(26)	ROOF SIDE RAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER		A-PILLAR
		• • •	B-PILLAR
(57)	BENEATH INSTRUMENT PANEL	• •	C-PILLAR
(53)	PARCEL TRAY	(17)	D-PILLAR
(48)	KNEE RESTRAINT	_	
(86)	VERTICAL CONSOLE	FLOOR	
		(40)	FLOOR
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(27)	CONSOLE ON FLOOR OR BETWEEN SEATS
		(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE
(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)	(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE
(65)	STEERING WHEEL	(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)
(66)	STEERING WHEEL COLUMN	(91)	KICKPANEL
(59)	TRANSMISSION LEVER ON COLUMN	, ,	
		Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)	(25)	ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)	(10)	_
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(26)	
(84)	PARKING BRAKE HANDLE IN FRONT	(24)	
(67)	IGNITION KEY	(18)	_
(06)	MIRROR	(39)	
	HEATER OR AIR CONDITIONING DUCTS		
(04)		(68)	
(01)	AIR CONDITIONING OR VENTILATION OUTLET(S)	(69)	ROLL BAR
(08)	RADIO (BUILT IN)	F	
(58)	ADD-ON TAPE DECK, RADIO, A/C		OR SURFACE OF CASE VEHICLE
(68)	ROOF MOUNTED CONTROLS/CONSOLES	(37)	
D		Δ.	(SPECIFIC AREA UNKNOWN)
REAR		(35)	HOOD OF CASE VEHICLE
(88)		(60)	EXTERIOR OF CASE VEHICLE (E.G.
(23)			OUTSIDE MIRRORS, ANTENNA, TRIM)
(39)	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
		(64)	TIRES OF CASE VEHICLE
Interior-General			
(11)	TRANSMISSION SELECTION LEVER (LOCATION UNK.)	BEYOND	CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN	(36)	AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
(07)	PARKING BRAKE HANDLE (LOCATION UNKNOWN)	(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(84)	PARKING BRAKE HANDLE IN FRONT	` '	OUTSIDE MIRRORS, ANTENNA, TRIM)
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
, ,	-,	(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
	FRONT SEAT CUSHION	(77)	TIRES OF OTHER VEHICLE
	REAR SEAT CUSHION & BACK	(78)	GROUND
	ARMREST ON SEAT	. (79)	WATER
(89)	UNDER SEAT BOTTOM	• •	
(03)	UNDER SEAT BOTTOW	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
(22)	DECTRAINT CYCTEM HADDWADE		OR WATER. PLEASE DESCRIBE.)
	RESTRAINT SYSTEM HARDWARE	D	0
	RESTRAINT SYSTEM WEBBING		ATING OBJECTS
٠,,	AIR CUSHION SKIN (AIRBAG)		OTHER VEHICLE
	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(72)	OBJECTS (DESCRIBE)
	AIRBAG GAS		
. ,	KNEE RESTRAINT	MISCELL	
	HEAD RESTRAINT	(00)	NO CONTACT (INVALID FIELD FORM CODE)
(42)	CHILD SEAT RESTRAINTS	(38)	OTHER (E.G. FIRE. DESCRIBE)
(43)		(90)	SPARE TIRE
	INTERIOR LOOSE OBJECT	(96)	INDUCED
	OTHER OCCUPANT(S)	(97)	EJECTED, UNKNOWN CONTACT
	INTERNAL FLYING GLASS (FROM ANY SOURCE)	(98)	IMPACT FORCE, "WHIPLASH",
(41)	UNKNOWN INTERIOR SURFACE		HYPEREXTENSION/COMPRESSION
		(00)	UNKNOWN AREA OF CONTACT
		(33)	CHAIR AND CONTACT



CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

1 BODY REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

SEVERITY 5 SYSTEM/ORGAN 4 LESION 9 ASPECT 0 BODY REGION 1

5 SEVERITY (OR "AIS", ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN



Control Chair

History Chair

History Chair

History Chair

Apphon

ian .



































































































PN 21800 #47